

DAMAGE IN CHRISTCHURCH AND CANTERBURY

P. J. Moss*

Introduction

For many people in Christchurch and other parts of Canterbury, the earthquake which occurred in the early hours of 24th May was marked by considerable shaking which lasted for about 35 seconds. In many cases the shaking was accompanied by some noise as the house moved with the earthquake. However, later conversation indicated that some people, at least, claimed that they were not woken at all by the earthquake and so showed that the earthquake was not very severe.

Initial newspaper reports showed that a little damage had been caused to commercial buildings in Christchurch - mainly cracked brickwork and plaster. The Lyttelton road and railway tunnels were undamaged, as were all railway bridges in Canterbury. No damage was reported from Timaru, Ashburton or other areas in South Canterbury.

Shortly after the earthquake it was noticed that the cross on the top of the Cathedral spire was moving as the bells were rung. Since two previous crosses had been damaged by earthquakes, earthquake damage was again suspected. Later examination showed however that the movement was due to the effects of weathering and time.

The extent of damage

Damage was light throughout the whole of the Canterbury area. The number of claims from the area handled by the Earthquake and War Damage Commission was as low as 600 compared with the several thousand that resulted from the April storm damage. Of the 600 claims, some 60% were for damage to chimneys. The remainder were mainly for cracking to walls and foundations, as well as roof damage.

In general, light damage occurred throughout North Canterbury while there was very little damage in South Canterbury. In addition to those areas shown in figure 1, some damage occurred in the area extending up to 20 miles south and southwest of Christchurch. Rangiora, 20-25 miles north of Christchurch appears to have been almost free from damage while areas further north were affected. Culverden and Waikari were damaged more extensively than Cheviot which has suffered considerable damage in previous earthquakes.

Few multistorey buildings exist in areas outside Christchurch. The damage to houses here was much the same in type as that which occurred in Christchurch. This included damage to chimneys (mainly double chimneys), roofs and ceilings (particularly around the chimney breast), and cracking of lathe and plaster walls and ceilings.

Damage in the Christchurch area

A rough analysis of the damage is given in Table 1.

In the Christchurch area, damage appears to have been confined to houses and the older masonry buildings. Damage was scattered throughout

* Lecturer, The University of Canterbury.

the built-up area and does not appear to predominate in any one area. Fig. 2 shows the scatter of damage to chimneys in Christchurch. No cases were reported of stock being thrown off shelves in shops.

The distribution of chimney damage throughout the area is shown in fig. 2. Damage of other types followed a similar pattern with no apparent preponderance in any one part of the built-up area.

Table 1

| <u>Type of Damage</u> | <u>Extent of Damage as percentage of total</u> |
|--------------------------------|--|
| Chimneys | 42% |
| Cracking to walls and ceilings | 28% |
| Roofs (tiles etc.) | 7% |
| Exterior | 4% |
| Foundations | 2% |
| Glass | 3% |
| Brick walls | 3% |
| General | 7% |
| Miscellaneous | 4% |

Detailed description of damage

(a) Commercial Buildings

Damage was very slight considering the extent of the commercial areas and the apparent lack of seismic resistance of some older masonry buildings.

In a number of older brick buildings mortar was shaken loose from the joints by the vibration of the earthquake. The danger here is that this may be one sign that the mortar has perished and no longer acts to bond the bricks together. In this case these buildings would be serious earthquake hazards should Christchurch experience an earthquake of similar or greater intensity. While it is known that there are badly cracked brick parapets on a number of buildings, only one parapet was further damaged to the extent that part of it collapsed. The particular building was of two-skin brickwork and 70-80 years old.

Only two of the many modern, new buildings appear to have been damaged in any way. These buildings were fully designed to the New Zealand building code and the damage was confined to cracking of masonry panels. The Government Life Building is a concrete encased steel building with glazing on the South and East Walls and brick infill panels on the North and West Walls. Hairline cracks appeared in $\frac{1}{4}$ inch thick plaster on the north walls at ceiling level from the second floor upwards. The third and fourth floors were the most affected, with cracking extending around to the west side. It appears that the cracks were present before the earthquake and the only true earthquake damage was a small amount of loose plaster that was shaken down by the vibration and the fretting of the mortar joints with the slight earthquake movement. The damage has been considered to be not worth repairing at this stage. No glazing in the building was even cracked.

The other building which suffered some damage was the Bank of New Zealand. Here some superficial cracking occurred in block infill panels, adjacent to the concrete encased steel columns. In addition,




FIGURE 1. The Canterbury area in relation to Inangahua and the West Coast.




FIGURE 2. Distribution of chimney damage in the Christchurch area. (Dots indicate damaged chimneys.) (Dash line indicates extent of urban area.)

