

# BULLETIN OF THE NEW ZEALAND SOCIETY FOR EARTHQUAKE ENGINEERING

## 3-YEAR INDEX 1999-2001

### Key to Bulletin Issues:

|      |          |           |      |                                                                                                                                                               |           |
|------|----------|-----------|------|---------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|
| Vol. | 32, No.1 | March     | 1999 | Brown, N. see Sharpe, R.D.                                                                                                                                    | 33(2)     |
|      | 32(2)    | June      |      | Brunsdon, D. NZSEE President's Page                                                                                                                           | 33(2) i   |
|      | 32(3)    | September |      | Brunsdon, D.R.: Davey, R.A.: Graham, C.J.: Sidwell,<br>G.K.: Villamor, P.: White, R.H.: Zhao, J.X.<br>The Chi-Chi, Taiwan Earthquake of 21<br>September 1999. | 33(2) 105 |
|      | 32(4)    | December  |      | Bubb, C.T.J. Earthquake engineering in Australia –<br>before Meckering and after Newcastle.                                                                   | 32(1) 13  |
|      | 33(1)    | March     | 2000 | Buckle, I.G. Passive control of structures for seismic<br>loads.                                                                                              | 33(3) 209 |
|      | 33(2)    | June      |      | Bull, D.K. see Singh, S.S.                                                                                                                                    | 32(2)     |
|      | 33(3)    | September |      |                                                                                                                                                               |           |
|      | 33(4)    | December  |      |                                                                                                                                                               |           |
|      | 34(1)    | March     | 2001 |                                                                                                                                                               |           |
|      | 34(2)    | June      |      |                                                                                                                                                               |           |
|      | 34(3)    | September |      |                                                                                                                                                               |           |
|      | 34(4)    | December  |      |                                                                                                                                                               |           |

### AUTHOR INDEX

#### A.

Arya, A.S. Non-engineered construction in developing countries- an approach toward earthquake risk prediction. 33(3) 187

#### B.

Barnett, A. see Goldsmith, P. 32(2)

Beattie, G. see Beetham, D. 34(4)

Beetham, D. : Beattie, G.: Earl, B.: Duncan, D. NZ Society for Earthquake Engineering Reconnaissance Team to Seattle, USA: The February 28, 2001 Nisqually Earthquake. 34(4) 253

Berrill, J.B. see Davis, R.O. 34(2)

Berryman, K.R. see Downes, G.L. 32(4)

Berryman, K. see Stirling, M. 34(4)

Bradshaw, D. see Sharpe, R.D. 33(2)

#### C.

Carr, A.J. see Crisafulli, F.J. 33(1)

Carr, A.J. see Rahman, A.M. 34(1)

Chadwick, M. see Kozuch, M.J. 32(3)

Charleson, A.W. A progress report on the Earthquake Hazard Centre. 32(4) 257

Charleson, A.W.: Fyfe, G.D. Earthquake building damage in developing countries: a review of recent reconnaissance reports. 34(2) 158

Cooke, N. see Singh, S.S. 32(2)

Cousins, W.J. : Zhao, J.X.: Perrin, N.D. A model for the attenuation of peak ground acceleration in New Zealand earthquakes based on seismograph and accelerograph data. 32(4) 193

Cowan, H.A. see Restrepo, J.I. 33(1)

Crisafulli, F.J.: Carr, A.J.: Park, R. Analytical modelling of infilled frame structures – a general review. 33(1) 30

- D.**
- Davenport, P.N. see Zhao, J.X. 32(3)
- Davenport, P.N. see Dowrick, D.J. 34(3)
- Davey, R.A. see Brunsdon, D.R. 33(2)
- Davidson, B.J. see Fenwick, R.C. 32(1)
- Davidson, B.J. see Ingham, J.M. 34(2)
- Davis, R.O.: Berrill, J.B. Liquefaction at the Imperial Valley Wildlife site. 34(2) 91
- Deam, B.L. Seismic ratings for degrading structural systems. 34(3) 214
- Dely, R. see Fenwick, R.C. 32(1)
- Downes, G.L.: Dowrick, D.J.: Smith, E.G.C.: Berryman, K.R. The 1934 Pahiatua Earthquake sequence: analysis of observational and instrumental data. 32(4) 221
- Downes, G.L.: Dowrick, D.J.: Van Dissen, R.J.: Taber, J.J.: Hancox, G.T.: Smith, E.G.C. The 1942 Wairarapa, New Zealand, Earthquakes: analysis of observational and instrumental data. 34(2) 125
- Downes, G. see Pettinga, J.R. 34(4)
- Dowrick, D.J. see Rhoades, D.A. 32(1)
- Dowrick, D.J.: Rhoades, D.A. Attenuation of Modified Mercalli Intensity in New Zealand earthquakes. 32(2) 55
- Dowrick, D.J. see Downes, G.L. 32(4)
- Dowrick, D.J. see Downes, G.L. 34(2)
- Dowrick, D.J.: Rhoades, D.A.: Davenport, P.N. Damage ratios for domestic property in the Magnitude 7.2 1968 Inangahua, New Zealand, Earthquake. 34(3) 191
- Duncan, D. see Beetham, D. 34(4)
- E.**
- Earl, B. see Beetham, D. 34(4)
- Elliott, S. see Goldsmith, P. 32(2)
- F.**
- Fenwick, R.C.: Dely, R.: Davidson, B.J. Ductility demand for uni-directional and reversing plastic hinges in ductile moment resisting frames. 32(1) 1
- Fyfe, G.D. see Charleson, A.W. 34(2)
- G.**
- Garcia, S.R. see Romo, M.P. 33(3)
- Goff, J. see Goldsmith, P. 32(2)
- Goldsmith, P.: Barnett, A.: Goff, J.: McSaveney, M.: Elliott, S.: Nongkas, M. Report of the New Zealand Reconnaissance Team to the area of the 17<sup>th</sup> July 1998 Tsunami at Sissano Lagoon, Papua New Guinea. 32(2) 102
- Graham, C.J. see Brunsdon, D.R. 33(2)
- H.**
- Hancox, G.T. see Downes, G.L. 34(2)
- Holmes, W.T. Risk assessment and retrofit of existing buildings. 33(3) 222
- I.**
- Ingham, J.M. see To, N.H.T. 33(3)
- Ingham, J.M.: Liddell, D.: Davidson, B.J. Influence of loading history on the response of a reinforced concrete beam. 34(2) 107
- J.**
- Jigyasu, R. From natural to cultural disaster: consequences of the post-earthquake rehabilitation process on the cultural heritage in Marathwada region, India. 34(3) 237
- Johnston, D. see Manville, V. 33(4)

**K.**

Kameda, H. Engineering management of lifeline systems under earthquake risk. 33(3) 248

Kawashima, K. Seismic design and retrofit of bridges. 33(3) 265

King, A.B. Report on attendance at ISO TC 98 'Bases for actions on structures', held in Washington DC, 14<sup>th</sup> to 19<sup>th</sup> May 2001. 34(3) 244

Kingsbury, P.A.: Pettinga, J.R.: Van Dissen, R.J. Earthquake hazard and risk assessment study for the Canterbury region: *Outline of programme development*. 34(4) 276

Kircher, C.A. United States building code approach to variations in regional seismicity. 33(1) 48

Kirkcaldie, D. see Sharpe, R.D. 33(2)

Kowalsky, M.J. see Priestley, M.J.N. 33(4)

Kozuch, M.J.: Chadwick, M. Azimuthal and regional variations of coda waves in New Zealand. 32(3) 170

**L.**

Liddell, D. see Ingham, J.M. 34(2)

Liu, A.: Park, R. Seismic behaviour and retrofit of pre-1970's as-built exterior beam-column joints reinforced by plain round bars. 34(1) 68

**M.**

Manville, V.: Johnston, D.: Stammers, S.: Scott, B. Comparative preparedness in New Zealand and the Philippines for response to, and recovery from, volcanic eruptions: case studies from the 1991 Pinatubo eruption and the 1995-96 eruptions of Ruapehu. 33(4) 445

Mattingly, S. Advances in seismic risk management in developing countries. 33(3) 286

McGinty, P. Preparation of the New Zealand earthquake catalogue for a probabilistic seismic hazard analysis. 34(1) 60

McManus, K.J. see Sharpe, R.D. 33(2)

McSaveney, M. see Goldsmith, P. 32(2)

McVerry, G.H. see Zhao, J.X. 32(3)

Medoza, M.J. see Romo, M.P. 33(3)

Megget, L.M. Editorial 32(4) Unpaged

Moss, P.J. see Rahman, A.M. 34(1)

**N.**

Nongkas, M. see Goldsmith, P. 32(2)

**P.**

Pancha, A.: Taber J. Weak motion attenuation of peak ground acceleration in the North Island, New Zealand. 32(3) 125

Park, R. see Crisafulli, F.J. 33(1)

Park, R. Brief report from the 12WCEE Organising Committee. 33(2) 169

Park, R. Brief report on the 12<sup>th</sup> World Conference on Earthquake Engineering, held in Auckland, New Zealand during 30 January – 4 February 2000. 33(3) 177

Park, R. Improving the resistance of structures to earthquakes. 34(1) 1

Park, R. see Liu, A. 34(1)

Paulay, T. Understanding torsional phenomena in ductile systems. 33(4) 403

Perrin, N.D. see Cousins, W.J. 32(4)

Pettinga, J.R. see Kingsbury, P.A. 34(4)

Pettinga, J.R.: Yetton, M.D.: Van Dissen, R.J.: Downes, G. Earthquake source identification and characterisation for the Canterbury region, South Island, New Zealand. 34(4) 282

Pettinga, J.R. see Stirling, M. 34(4)

Pham, T. see Sharpe, R.D. 33(2)

- Pinto, P.E. Design for low/moderate seismic risk. 33(3) 303
- Priestley, M.J.N. Performance based seismic design. 33(3) 325
- Priestley, M.J.N.: Kowalsky, M.J. Direct displacement-based seismic design of concrete buildings. 33(4) 421
- R.**
- Rahman, A.M.: Carr, A.J.: Moss, P.J. Seismic pounding of a case of adjacent multiple-storey buildings of differing total heights considering soil flexibility effects. 34(1) 40
- Restrepo, J.I.: Cowan, H.A. The "Eje Cafetero" Earthquake, Colombia of January 25 1999. 33(1) 1
- Reyners, M. Quantifying the hazard of large subduction thrust earthquakes in Hawke's Bay. 33(4) 477
- Rhoades, D.A.: Dowrick, D.J. Station correction analysis for surface-wave magnitudes of New Zealand earthquakes. 32(1) 21
- Rhoades, D.A. see Dowrick, D.J. 32(2)
- Rhoades, D.A. see Dowrick, D.J. 34(3)
- Romo, M.P.: Mendoza, M.J.: Garcia, S.R. Geotechnical factors in seismic design of foundations, state-of-the-art report. 33(3) 347
- S.**
- Scott, B. see Manville, V. 33(4)
- Scott, E.F. A report on the relief organisation in Hastings arising out of the [Magnitude 7.8] Earthquake in Hawke's Bay [New Zealand] on February 3, 1931. 32(4) 246
- Sharpe, R.D.: Bradshaw, D.: Brown, N.: Van Dissen, R.: Kirkcaldie, D.: McManus, K.J.: Pham, T.: Stevenson, C. Marmara Sea Earthquake Reconnaissance Report. 33(2) 65
- Sidwell, G.K. see Brunson, D.R. 33(2)
- Singh, S.S.: Cooke, N.: Bull, D.K. Out-of-plane performance of a partially filled reinforced masonry wall with Ribraft<sup>TM</sup> floor. 32(2) 90
- Smith, E.G.C. see Downes, G.L. 32(4)
- Smith, E.G.C. see Downes, G.L. 34(2)
- Somerville, P. Seismic hazard evaluation. 33(3) 371
- Somerville, P. **Addendum:** Figures for the 12WCEE state-of-the-art paper "Seismic hazard evaluation" published in Vol. 33, No. 3, September 2000, pp325-346. 33(4) 484
- Soong, T.T.: Spencer, B.F. Active, semi-active and hybrid control of structures. 33(3) 387
- Spencer, B.F. see Soong, T.T. 33(3)
- Sritharan, S. see To, N.H.T. 34(3)
- Stammers, S. see Manville, V. 33(4)
- Stevenson, C. see Sharpe, R.D. 33(2)
- Stirling, M.: Pettinga, J.R.: Berryman, K.: Yetton, M.D. Probabilistic seismic hazard assessment of the Canterbury region, New Zealand. 34(4) 318
- T.**
- Taber, J. see Pancha, A. 32(3)
- Taber, J.J. see Downes, G.L. 34(2)
- To, N.H.T.: Ingham, J.M.: Sritharan, S. Monotonic non-linear analysis of reinforced concrete knee joints using strut-and-tie computer models. 34(3) 169
- V.**
- Van Dissen, R. see Sharpe, R.D. 33(2)
- Van Dissen, R.J. see Downes, G.L. 34(2)
- Van Dissen, R.J. see Kingsbury, P.A. 34(4)
- Van Dissen, R.J. see Pettinga, J.R. 34(4)

Villamor, P. see Brunson, D.R. 33(2)

## W.

White, R.H. see Brunson, D.R. 33(2)

## Y.

Yetton, M.D. see Pettinga, J.R. 34(4)

Yetton, M.D. see Stirling, M. 34(4)

## Z.

Zhao, J.X.; Davenport, P.N.; McVerry, G.H. Modelling and earthquake response of Gisborne Post office site, New Zealand. 32(3) 146

Zhao, J.X. see Cousins, W.J. 32(4)

Zhao, J.X. see Brunson, D.R. 33(2)

---

## SUBJECT INDEX

### Addendum

Figures for the 12WCEE state-of-the-art paper "Seismic hazard evaluation" published in Vol. 33, No. 3, September 2000, pp325-346. Somerville, P. 33(4) 484

**Base Isolation** – see Earthquake engineering

### Bridges

Monotonic non-linear analysis of reinforced concrete knee joints using strut-and-tie computer models. To, N.H.T.; Ingham, J.M.; Sritharan, S. 34(3) 169

Seismic design and retrofit of bridges. Kawashima, K. 33(3) 265

### Buildings

Analytical modelling of infilled frame structures – a general review. Crisafulli, F.J.; Carr, A.J.; Park, R. 33(1) 30

Damage ratios for domestic property in the Magnitude 7.2 1968 Inangahua, New Zealand, Earthquake. Dowrick, D.J.; Rhoades, D.A.; Davenport, P.N. 34(3) 191

Improving the resistance of structures to earthquakes. Park, R. 34(1) 1

Risk assessment and retrofit of existing buildings. Holmes, W.T. 33(3) 222

Seismic behaviour and retrofit of pre-1970's as-built exterior beam-column joints reinforced by plain round bars. Liu, A.; Park, R. 34(1) 68

Seismic pounding of a case of adjacent multiple-storey buildings of differing total heights considering soil flexibility effects. Rahman, A.M.; Carr, A.J.; Moss, P.J. 34(1) 40

Understanding torsional phenomena in ductile systems. Paulay, T. 33(4) 403

**Codes** see Standards

### Conferences and seminars

Brief report from the 12WCEE Organising Committee. Park, R. 33(2) 169

Brief report on the 12<sup>th</sup> World Conference on Earthquake Engineering, held in Auckland, New Zealand during 30 January – 4 February 2000. Park, R. 33(3) 177

Report on attendance at ISO TC 98 'Bases for actions on structures', held in Washington DC, 14<sup>th</sup> to 19<sup>th</sup> May 2001. King, A.B. 34(3) 244

### Disaster relief

- A report on the relief organisation in Hastings arising out of the [Magnitude 7.8] Earthquake in Hawke's Bay [New Zealand] on February 3, 1931.  
Scott, E.F. 32(4) 246
- Comparative preparedness in New Zealand and the Philippines for response to, and recovery from, volcanic eruptions: case studies from the 1991 Pinatubo eruption and the 1995-96 eruptions of Ruaphehu. Manville, V.: Johnston, D.: Stammers, S.: Scott, B. 33(4) 445
- Earthquake damage**
- Damage ratios for domestic property in the Magnitude 7.2 1968 Inangahua, New Zealand, Earthquake. Dowrick, D.J.: Rhoades, D.A.: Davenport, P.N. 34(3) 191
- Earthquake building damage in developing countries: a review of recent reconnaissance reports. Charleson, A.W.: Fyfe, G.D. 34(2) 158
- From natural to cultural disaster: consequences of the post-earthquake rehabilitation process on the cultural heritage in Marathwada region, India. Jigyasu, R. 34(3) 237
- Marmara Sea Earthquake Reconnaissance Report. Sharpe, R.D.: Bradshaw, D.: Brown, N.: Van Dissen, R.: Kirkcaldie, D.: McManus, K.J.: Pham, T.: Stevenson, C. 33(2) 65
- The "Eje Cafetero" Earthquake, Colombia of January 25 1999. Restrepo, J.I.: Cowan, H.A. 33(1) 1
- Earthquake engineering**
- Active, semi-active and hybrid control of structures. Soong, T.T.: Spencer, B.F. 33(3) 387
- Analytical modelling of infilled frame structures – a general review. Crisafulli, F.J.: Carr, A.J.: Park, R. 33(1) 30
- Design for low/moderate seismic risk. Pinto, P.E. 33(3) 303
- Direct displacement-based seismic design of concrete buildings. Priestley, M.J.N.: Kowalsky, M.J. 33(4) 421
- Ductility demand for uni-directional and reversing plastic hinges in ductile moment resisting frames. Fenwick, R.C.: Dely, R.: Davidson, B.J. 32(1) 1
- Earthquake engineering in Australia – before Meckering and after Newcastle. Bubb, C.T.J. 32(1) 13
- Geotechnical factors in seismic design of foundations, state-of-the-art report. Romo, M.P.: Mendoza, M.J.: Garcia, S.R. 33(3) 347
- Improving the resistance of structures to earthquakes. Park, R. 34(1) 1
- Influence of loading history on the response of a reinforced concrete beam. Ingham, J.M.: Liddell, D.: Davidson, B.J. 34(2) 107
- Monotonic non-linear analysis of reinforced concrete knee joints using strut-and-tie computer models. To, N.H.T.: Ingham, J.M.: Sritharan, S. 34(3) 169
- Out-of-plane performance of a partially filled reinforced masonry wall with Ribraft™ floor. Singh, S.S.: Cooke, N.: Bull, D.K. 32(2) 90
- Passive control of structures for seismic loads. Buckle, I.G. 33(3) 209
- Performance based seismic design. Priestley, M.J.N. 33(3) 325
- Report on attendance at ISO TC 98 'Bases for actions on structures', held in Washington DC, 14<sup>th</sup> to 19<sup>th</sup> May 2001. King, A.B. 34(3) 244
- Seismic behaviour and retrofit of pre-1970's as-built exterior beam-column joints reinforced by plain round bars. Liu, A.: Park, R. 34(1) 68
- Seismic design and retrofit of bridges. Kawashima, K. 33(3) 265
- Seismic pounding of a case of adjacent multiple-storey buildings of differing total heights considering soil flexibility effects. Rahman, A.M.: Carr, A.J.: Moss, P.J. 34(1) 40
- Understanding torsional phenomena in ductile systems. Paulay, T. 33(4) 403

|                                                                                                                                                             |           |                                                                                                                                                                                        |           |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|
| United States building code approach to variations in regional seismicity. Kircher, C.A.                                                                    | 33(1) 48  | - April to June 1999                                                                                                                                                                   | 32(3) 190 |
|                                                                                                                                                             |           | - July to September 1999                                                                                                                                                               | 32(4) 263 |
| <b>Earthquakes general</b>                                                                                                                                  |           | - 1999 October – December                                                                                                                                                              | 33(1) 60  |
| The “Eje Cafetero” Earthquake, Colombia of January 25 1999. Restrepo, J.I.: Cowan, H.A.                                                                     | 33(1) 1   | - January – April 2000                                                                                                                                                                 | 33(2) 173 |
| World earthquake of magnitude 6.0 or greater:                                                                                                               |           | - May – August 2000                                                                                                                                                                    | 33(4) 498 |
| - November 1998 – December 1998                                                                                                                             | 32(1) 40  | - September – December 2000                                                                                                                                                            | 34(1) 87  |
| - January to March 1999                                                                                                                                     | 32(2) 121 | - January – March 2001                                                                                                                                                                 | 34(2) 167 |
| - April to May 1999                                                                                                                                         | 32(3) 189 | - April – June 2001                                                                                                                                                                    | 34(3) 251 |
| - July – September 1999                                                                                                                                     | 32(4) 262 | - July – September 2001                                                                                                                                                                | 34(4) 343 |
| - October – December 1999                                                                                                                                   | 33(1) 57  | Station correction analysis for surface-wave magnitudes of New Zealand earthquakes. Rhoades, D.A.: Dowrick, D.J.                                                                       | 32(1) 21  |
| - January – April 2000                                                                                                                                      | 33(2) 172 | The 1934 Pahiatua Earthquake sequence: analysis of observational and instrumental data. Downes, G.L.: Dowrick, D.J.: Smith, E.G.C.: Berryman, K.R.                                     | 32(4) 221 |
| - April 18 – August 2000                                                                                                                                    | 33(4) 494 | The 1942 Wairarapa, New Zealand, Earthquakes: analysis of observational and instrumental data. Downes, G.L.: Dowrick, D.J.: Van Dissen, R.J.: Taber, J.J.: Hancox, G.T.: Smith, E.G.C. | 34(2) 125 |
| - September – December 2000                                                                                                                                 | 34(1) 83  |                                                                                                                                                                                        |           |
| - January – March 2001                                                                                                                                      | 34(2) 165 |                                                                                                                                                                                        |           |
| - April – June 2001                                                                                                                                         | 34(3) 249 |                                                                                                                                                                                        |           |
| - July – September 2001                                                                                                                                     | 34(4) 342 |                                                                                                                                                                                        |           |
| <b>Earthquakes in New Zealand</b>                                                                                                                           |           | <b>Earthquake mitigation</b>                                                                                                                                                           |           |
| A report on the relief organisation in Hastings arising out of the [Magnitude 7.8] Earthquake in Hawke’s Bay [New Zealand] on February 3, 1931. Scott, E.F. | 32(4) 246 | A progress report on the Earthquake Hazard Centre. Charleson, A.W.                                                                                                                     | 32(4) 257 |
| Damage ratios for domestic property in the Magnitude 7.2 1968 Inangahua, New Zealand, Earthquake. Dowrick, D.J.: Rhoades, D.A.: Davenport, P.N.             | 34(3) 191 | <b>Earthquake risk (includes risk management)</b>                                                                                                                                      |           |
| Quantifying the hazard of large subduction thrust earthquakes in Hawke’s Bay. Reyners, M.                                                                   | 33(4) 477 | Advances in seismic risk management in developing countries. Mattingly, S.                                                                                                             | 33(3) 286 |
| Significant New Zealand Earthquakes:                                                                                                                        |           | Design for low/moderate seismic risk. Pinto, P.E.                                                                                                                                      | 33(3) 303 |
| - November 1998 to December 1998                                                                                                                            | 32(1) 41  | Earthquake hazard and risk assessment study for the Canterbury region: <i>Outline of programme development</i> . Kingsbury, P.A.: Pettinga, J.R.: Van Dissen, R.J.                     | 34(4) 276 |
| - January to March 1999                                                                                                                                     | 32(2) 123 |                                                                                                                                                                                        |           |

Earthquake source identification and characterisation for the Canterbury region, South Island, New Zealand. Pettinga, J.R.: Yetton, M.D.: Van Dissen, R.J.: Downes, G. 34(4) 282

Non-engineered construction in developing countries- an approach toward earthquake risk prediction. Arya, A.S. 33(3) 187

Preparation of the New Zealand earthquake catalogue for a probabilistic seismic hazard analysis. McGinty, P. 34(1) 60

Probabilistic seismic hazard assessment of the Canterbury region, New Zealand. Stirling, M.: Pettinga, J.R.: Berryman, K.: Yetton, M.D. 34(4) 318

Risk assessment and retrofit of existing buildings. Holmes, W.T. 33(3) 222

#### Editorials and leading articles

Editorial. Megget, L.M. 32(4) Unpaged

NZSEE President's Page. Brunson, D. 33(2) i

#### General

From natural to cultural disaster: consequences of the post-earthquake rehabilitation process on the cultural heritage in Marathwada region, India. Jigyasu, R. 34(3) 237

#### Geomechanics/Geotechnical engineering

Geotechnical factors in seismic design of foundations, state-of-the-art report. Romo, M.P.: Mendoza, M.J.: Garcia, S.R. 33(3) 347

Liquefaction at the Imperial Valley Wildlife site. Davis, R.O.: Berrill, J.B. 34(2) 91

Modelling and earthquake response of Gisborne Post office site, New Zealand. Zhao, J.X.; Davenport, P.N.: McVerry, G.H. 32(3) 146

Seismic pounding of a case of adjacent multiple-storey buildings of differing total heights considering soil flexibility effects. Rahman, A.M.: Carr, A.J.: Moss, P.J. 34(1) 40

#### Lifelines

Engineering management of lifeline systems under earthquake risk. Kameda, H. 33(3) 248

#### Masonry

Analytical modelling of infilled frame structures – a general review. Crisafulli, F.J.: Carr, A.J.: Park, R. 33(1) 30

Out-of-plane performance of a partially filled reinforced masonry wall with Ribraft<sup>TM</sup> floor. Singh, S.S.: Cooke, N.: Bull, D.K. 32(2) 90

#### Modified Mercalli intensity

Attenuation of Modified Mercalli Intensity in New Zealand earthquakes. Dowrick, D.J.: Rhoades, D.A. 32(2) 55

#### New Zealand Society for earthquake Engineering (see also Reconnaissance reports)

Marmara Sea Earthquake Reconnaissance Report. Sharpe, R.D.: Bradshaw, D.: Brown, N.: Van Dissen, R.: Kirkcaldie, D.: McManus, K.J.: Pham, T.: Stevenson, C. 33(2) 65

NZ Society for Earthquake Engineering Reconnaissance Team to Seattle, USA: The February 28, 2001 Nisqually Earthquake. Beetham, D.: Beattie, G.: Earl, B.: Duncan, D. 34(4) 253

Report of the New Zealand Reconnaissance Team to the area of the 17<sup>th</sup> July 1998 Tsunami at Sissano Lagoon, Papua New Guinea. Goldsmith, P.: Barnett, A.: Goff, J.: McSaveney, M.: Elliott, S.: Nongkas, M. 32(2) 102

The Chi-Chi, Taiwan Earthquake of 21 September 1999. Brunson, D.R.: Davey, R.A.: Graham, C.J.: Sidwell, G.K.: Villamor, P.: White, R.H.: Zhao, J.X. 33(2) 105

The "Eje Cafetero" Earthquake, Colombia of January 25 1999. Restrepo, J.I.: Cowan, H.A. 33(1) 1

### Reconnaissance reports

Comparative preparedness in New Zealand and the Philippines for response to, and recovery from, volcanic eruptions: case studies from the 1991 Pinatubo eruption and the 1995-96 eruptions of Ruaphehu. Manville, V.: Johnston, D.: Stammers, S.: Scott, B. 33(4) 445

Earthquake building damage in developing countries: a review of recent reconnaissance reports. Charleson, A.W.: Fyfe, G.D. 34(2) 158

Marmara Sea Earthquake Reconnaissance Report. Sharpe, R.D.: Bradshaw, D.: Brown, N.: Van Disen, R.: Kirkcaldie, D.: McManus, K.J.: Pham, T.: Stevenson, C. 33(2) 65

NZ Society for Earthquake Engineering Reconnaissance Team to Seattle, USA: The February 28, 2001 Nisqually Earthquake. Beetham, D.: Beattie, G.: Earl, B.: Duncan, D. 34(4) 253

Report of the New Zealand Reconnaissance Team to the area of the 17<sup>th</sup> July 1998 Tsunami at Sissano Lagoon, Papua New Guinea. Goldsmith, P.: Barnett, A.: Goff, J.: McSaveney, M.: Elliott, S.: Nongkas, M. 32(2) 102

The Chi-Chi, Taiwan Earthquake of 21 September 1999. Brunson, D.R.: Davey, R.A.: Graham, C.J.: Sidwell, G.K.: Villamor, P.: White, R.H.: Zhao, J.X. 33(2) 105

The "Eje Cafetero" Earthquake, Colombia of January 25 1999. Restrepo, J.I.: Cowan, H.A. 33(1) 1

### Refurbishment and retrofitting

From natural to cultural disaster: consequences of the post-earthquake rehabilitation process on the cultural heritage in Marathwada region, India. Jigyasu, R. 34(3) 237

Risk assessment and retrofit of existing buildings. Holmes, W.T. 33(3) 222

### Reinforced concrete

Direct displacement-based seismic design of concrete buildings. Priestley, M.J.N.: Kowalsky, M.J. 33(4) 421

Ductility demand for uni-directional and reversing plastic hinges in ductile moment resisting frames. Fenwick, R.C.: Dely, R.: Davidson, B.J. 32(1) 1

Improving the resistance of structures to earthquakes. Park, R. 34(1) 1

Influence of loading history on the response of a reinforced concrete beam. Ingham, J.M.: Liddell, D.: Davidson, B.J. 34(2) 107

Monotonic non-linear analysis of reinforced concrete knee joints using strut-and-tie computer models. To, N.H.T.: Ingham, J.M.: Sritharan, S. 34(3) 169

Seismic behaviour and retrofit of pre-1970's as-built exterior beam-column joints reinforced by plain round bars. Liu, A.: Park, R. 34(1) 68

### Research (includes testing)

Ductility demand for uni-directional and reversing plastic hinges in ductile moment resisting frames. Fenwick, R.C.: Dely, R.: Davidson, B.J. 32(1) 1

Influence of loading history on the response of a reinforced concrete beam. Ingham, J.M.: Liddell, D.: Davidson, B.J. 34(2) 107

Out-of-plane performance of a partially filled reinforced masonry wall with Ribraft<sup>TM</sup> floor. Singh, S.S.: Cooke, N.: Bull, D.K. 32(2) 90

Projects to be funded by the Earthquake Commission Research Programme 1999/2000 32(3) 182

Projects to be funded by the Earthquake Commission Research Programme 2001/2002 34(4) 336

Seismic behaviour and retrofit of pre-1970's as-built exterior beam-column joints reinforced by plain round bars. Liu, A.: Park, R. 34(1) 68

Seismic ratings for degrading structural systems.  
Deam, B.L. 34(3) 214

### Seismic analysis and response

Active, semi-active and hybrid control of structures.  
Soong, T.T.: Spencer, B.F. 33(3) 387

Analytical modelling of infilled frame structures – a general review. Crisafulli, F.J.: Carr, A.J.: Park, R. 33(1) 30

Monotonic non-linear analysis of reinforced concrete knee joints using strut-and-tie computer models. To, N.H.T.: Ingham, J.M.: Sritharan, S. 34(3) 169

Seismic ratings for degrading structural systems.  
Deam, B.L. 34(3) 214

Understanding torsional phenomena in ductile systems.  
Paulay, T. 33(4) 403

### Seismic design

Active, semi-active and hybrid control of structures.  
Soong, T.T.: Spencer, B.F. 33(3) 387

Design for low/moderate seismic risk. Pinto, P.E. 33(3) 303

Direct displacement-based seismic design of concrete buildings. Priestley, M.J.N.: Kowalsky, M.J. 33(4) 421

Ductility demand for uni-directional and reversing plastic hinges in ductile moment resisting frames. Fenwick, R.C.: Dely, R.: Davidson, B.J. 32(1) 1

Geotechnical factors in seismic design of foundations, state-of-the-art report. Romo, M.P.: Mendoza, M.J.: Garcia, S.R. 33(3) 347

Improving the resistance of structures to earthquakes. Park, R. 34(1) 1

Influence of loading history on the response of a reinforced concrete beam. Ingham, J.M.: Liddell, D.: Davidson, B.J. 34(2) 107

Non-engineered construction in developing countries- an approach toward earthquake risk prediction. Arya, A.S. 33(3) 187

Out-of-plane performance of a partially filled reinforced masonry wall with Ribraft<sup>TM</sup> floor. Singh, S.S.: Cooke, N.: Bull, D.K. 32(2) 90

Performance based seismic design. Priestley, M.J.N. 33(3) 325

Seismic design and retrofit of bridges. Kawashima, K. 33(3) 265

Seismic ratings for degrading structural systems.  
Deam, B.L. 34(3) 214

Understanding torsional phenomena in ductile systems.  
Paulay, T. 33(4) 403

### Seismic hazards (includes hazard analysis)

Figures for the 12WCEE state-of-the-art paper “Seismic hazard evaluation” published in Vol. 33, No. 3, September 2000, pp325-346. Somerville, P. 33(4) 484

Preparation of the New Zealand earthquake catalogue for a probabilistic seismic hazard analysis. McGinty, P. 34(1) 60

Quantifying the hazard of large subduction thrust earthquakes in Hawke’s Bay. Reyners, M. 33(4) 477

Seismic hazard evaluation. Somerville, P. 33(3) 371

### Seismology

A model for the attenuation of peak ground acceleration in New Zealand earthquakes based on seismograph and accelerograph data. Cousins, W.J.: Zhao, J.X.: Perrin, N.D. 32(4) 193

Attenuation of Modified Mercalli Intensity in New Zealand earthquakes. Dowrick, D.J.: Rhoades, D.A. 32(2) 55

