

New Zealand Society for Earthquake Engineering

Corrigenda No. 1 dated 4 August 2008 for

Assessment and Improvement of the Structural Performance for Buildings in Earthquakes:

Prioritisation, Initial Evaluation, Detailed Assessment, Improvement Measures
Recommendations of NZSEE Study Group on Earthquake Risk Buildings
June 2006

Page 3-7, Table IEP-2, Note 1

Delete:

“Note 1: For buildings designed prior to 1976 and know to be designed as public buildings in accordance with the code of the time, multiply $(\%NBS)_{nom}$ by 1.25”

Substitute:

“Note 1: For buildings designed prior to 1965 and known to be designed as public buildings in accordance with the code of the time, multiply $(\%NBS)_{nom}$ by 1.25.

For buildings designed 1965 - 1976 and known to be designed as public buildings in accordance with the code of the time, multiply $(\%NBS)_{nom}$ by
1.33 - Zone A
1.2 - Zone B”

Page 3-12, Table 3.1: Return period scaling factor, Return Period Scaling Factor, C

Delete: column “1965 - 76”

Substitute:

1965 - 76
2
1
0.8
0.6