

## ERRATA

Two omissions occurred in editing the last issue of the Bulletin. These were:

Vol. 26, No.2, June 1993, pp185-191

### "Strengthening of the Wellington Town Hall", R.D. Jury

The last line was omitted from Reference 5. The full list of references should read as follows:

#### REFERENCES

1. Toomath, W., "Wellington's Old Town Hall", an independent survey of historical, architectural and structural influences on the preservation issue, commissioned by the Wellington Regional Committee of The New Zealand Historic Places Trust, March 1978
2. "Town Hall for the 21st Century - Wellington, New Zealand", Wellington City Council, 1992

3. NZS 1900 Chapter 8:1965, Basic Design Loads, New Zealand Standard Model Building Bylaw.
4. Priestley, MJN "Seismic Behaviour of Unreinforced Masonry Walls," Bulletin NZNSEE, Vol 18, No 2, June 1986 (also discussion in Bulletin NZNSEE Vol. 19, No. 1, March 1986)
5. "Earthquake Risk Buildings - Recommendations and Guidelines for Strengthening, Interim Securing and Strengthening", New Zealand National Society for Earthquake Engineering, December 1985

Vol. 26, No. 2, June 1993, pp194-207

### "An Evaluation of the New Zealand Torsional Code Provision", W.K. Tso and C.M. Wong

Figures 12 and 13 referred to on p. 205 of the paper were omitted and these are now included below.






Figure 12 Loading cases to evaluate the edge displacement criterion



(a)



(b)

Figure 13 Minimum torsional stiffness to satisfy the edge displacement criterion